


3C9C



00684.003533

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Where Patent of:

Tatsunori ISHIYAMA, et al.

U.S. Patent No.: 6,987,939 B2

Issued: January 17, 2006

Appl. No.: 10/676,106

Filed: October 2, 2003

For: IMAGE FORMING APPARATUS
WITH TWO CLEANING ELECTRIC
FIELDS FOR TRANSFERRING
DEVELOPER FROM A DEVELOPER
CHARGING DEVICE ONTO AN
IMAGE BEARING MEMBER

Examiner: Susan Lee

Group Art Unit: 2852

Confirmation No.: 8400

May 4, 2006

Certificate

MAY 08 2006

of Correction

Commissioner for Patents
Post Office Box 1450
Alexandria, VA 22313-1450

**REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

05/05/2006 JADD01 00000071 6987939

01 FC:1811


100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

MAY 8 2006

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our New York office at the address given below.

Respectfully submitted,


William M. Wannisky
Attorney for Patentees
Registration No. 28,373

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

WMW\tas

DC_MAIN 239547v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,987,939 B2

DATED : January 17, 2006

INVENTOR(S) : Tatsunori ISHIYAMA, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS:

In Figure 3, "OUNT" should read --COUNT--.

COLUMN 1:

Line 10, "relate" should read --relates--.

COLUMN 2:

Line 19, "an" should read --in--; and
Line 60, "in" (first occurrence) should read --is--.

COLUMN 3:

Line 25, "case" should read --case of--.

COLUMN 6:

Line 40, "an" should read --on--.

COLUMN 7:

Line 12, "t" should read --to--;
Line 35, "bing" should read --being--; and
Line 60, "recovered" should read --been recovered--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,987,939 B2

No. of add'l. copies
@ 30¢ per page



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,987,939 B2

DATED : January 17, 2006

INVENTOR(S) : Tatsunori ISHIYAMA, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 45, "is" should read --be--;
Line 53, "Job" should read --job--; and
Line 58, "detective" should read --defective--.

COLUMN 14:

Line 18, "By" should read --8y--; and
Line 36, "The" should read --¶ The--.

COLUMN 15:

Line 30, "different" should read --difference--.

COLUMN 16:

Line 37, "is" should read --be--; and
Line 55, "to" should be deleted.

COLUMN 18:

Line 6, "and" should read --and ¶--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,987,939 B2

No. of add'l. copies
@ 30¢ per page



2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,987,939 B2

DATED : January 17, 2006

INVENTOR(S) : Tatsunori ISHIYAMA, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS:

In Figure 3, "OUNT" should read --COUNT--.

COLUMN 1:

Line 10, "relate" should read --relates--.

COLUMN 2:

Line 19, "an" should read --in--; and
Line 60, "in" (first occurrence) should read --is--.

COLUMN 3:

Line 25, "case" should read --case of--.

COLUMN 6:

Line 40, "an" should read --on--.

COLUMN 7:

Line 12, "t" should read --to--;
Line 35, "bing" should read --being--; and
Line 60, "recovered" should read --been recovered--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,987,939 B2

No. of add'l. copies
@ 30¢ per page

MAY 8 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,987,939 B2

DATED : January 17, 2006

INVENTOR(S) : Tatsunori ISHIYAMA, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 10:

Line 45, "is" should read --be--;
Line 53, "Job" should read --job--; and
Line 58, "detective" should read --defective--.

COLUMN 14:

Line 18, "By" should read --8y--; and
Line 36, "The" should read --¶ The--.

COLUMN 15:

Line 30, "different" should read --difference--.

COLUMN 16:

Line 37, "is" should read --be--; and
Line 55, "to" should be deleted.

COLUMN 18:

Line 6, "and" should read --and ¶--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,987,939 B2

No. of add'l. copies
@ 30¢ per page